FOLLOWING DATA TO BE ANSWERED BY INSPECTOR N^{o} 7225 AND SIGNED WHEN RETURNED

DATE INSPECTED 4-28-60	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 12/4	•
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH ACROSS From MH 7/2 D =
WAS LATERAL AT CURBI VCS	ing ang Miller ng Miller ng Garday ng Banghar ng Propinsi Ang Propinsi Pro Propinsi ng Miller ng Miller ng Propinsi ng Propinsi ng Miller ng Miller ng Miller ng Miller ng Miller ng Mille
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR G. Seiden
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
	Prophint 12/2000
200 18 18 18 18 18 18 18 18 18 18 18 18 18	the defended on the later the Corner of the entire of the control of the corner of the
	15084110 58
SIGNED ROY Northa	D SEILED AT ENGINEER'S OFFICE
inspector for c	នៃ ស្នានៃស្នានី ស្នាន់ អនុស្រីស្នាន់ និះ ស្ត្រាស់នៅរបស់ នៃកាននៃក្រក

Nº 7225

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

The second of th
MASSILLON, OHIO, /Ø./ 19
RECEIVED OF Sell Sedon FEE OF \$ 50
FOR WHICH PERMISSION IS GRANTED HALLIMAK & PARALLI
TO TAP AMM SEWER ON THE LAST
OF Miles MU AVE. TYPE OF STREET HAND Allerface
THE PREMISES BEING LOT NO. 8949-57) PT 68, HOUSE NO. 1214
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL.
NAME OF CONTRACTOR SERVICE.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.