

No. 7233

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-27-55

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

200' EAST OF M₁ 7 1/2

HOUSE NO. 1418

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

A. D. Quinn

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

JAMES E. KIRBY

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

KIRBY INSPECTED THIS LINE IN 1955 DIDN'T HAVE A PERMIT
APPROX MEASUREMENTS PEOPLE MOVED IN HOUSE MARCH-19.

Diana should have taken this permit

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 7233

PERMIT TO TAP SEWER

MASSILLON, OHIO,

5/10 5-30-60

19

RECEIVED OF

V. Berdine

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

same (Dexter) Lamber

TO TAP

San

SEWER ON THE

N.

OF

Woodland St

AVE.

ST. TYPE OF STREET

dr

THE PREMISES BEING LOT NO.

1416

HOUSE NO.

1418

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Diana

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.