Nº 7236

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-25-60	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 24 N. 65M 8 Deer
WAS LATERAL AT CURB? Ves	
WAS ATTACHED TO MAIN NO	NAME OF CONTRACTOR DPOGERS
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
and the second of the second o	12',
	N = 150
· · · · · · · · · · · · · · · · · · ·	\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
SIGNED Por Latha	FILED AT ENGINEER'S OFFICE
REMARKS	Y and single in the sign and sign and sign and like the sign and the s

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/10/18 19
RECEIVED OF MANY 1 COURS FEE OF \$ 50
FOR WHICH PERMISSION IS GRANTED WHATEN KELLEY
TO TAP
OF MINAIMOIN ST. TYPE OF STREET der A
THE PREMISES BEING LOT NO. $1/938$, House No. 801
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR A CARO, & BARRO
HAME OF CONTRACTOR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.