Nº 7241

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-26-6	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 945	<u>-</u>	1 dear and out GINEN
SIZE OF PIPE USED 61	DISTANCE FROM FIRST MANHOLE 149 DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	FOURD SHE CHO Dec
WAS LATERAL AT CURB? V-C 5	andra andra a <u>la da andra de la Maria de Maria.</u> -	
WAS ATTACHED TO MAIN // Ö	NAME OF CONTRACTOR	# URBAN
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED	
garana da karanan karangan kanan da karangan da karangan da karangan da karangan da karangan da karangan da ka Bangan da karangan da kara	and the state of t	8
and the second second	And the second s	
The second secon	The second secon	32
	 The support of the control of the cont	5 × 6/2 PP
and the second second	ا (۱۹۶۲ ه.) - ۱۹۶۲ ه.)	
SIGNED Roy Lathor	FILED AT ENGINEE	R'S OFFICE
Y INSPECTOR FOR C	Walling Marine Society 2009	windian diam
REMARKS	<u> </u>	

THE CONTROL OF THE CONTROL OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Nº 7241

MASSILLON, OHIO, May 26 19
RECEIVED OF THATAL BY HALAM FEE OF 5 5
OR WHICH PERMISSION IS GRANTED 411 970 Anthrone
O TAP DAIL SEWER ON THE 1101A
of 11th 16 AVE. TYPE OF STREET HAYA SUNJACE
HE PREMISES BEING LOT NO. 2700 HOUSE NO. 945

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.