Nº 7250

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-9-60	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 5-40	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH  3/2/3-
WAS LATERAL AT CURBI VPS	the state of the s
WAS ATTACHED TO MAIN // 0	NAME OF CONTRACTOR AUDIANA
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	3/2 p = 4
SIGNED ROY VATION INSPECTOR FOR CIT	7 FILED AT ENGINEER'S OFFICE

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 7250

## PERMIT TO TAP SEWER

	Massillon, Ohio	, 6/g	19
RECEIVED OF	1 1	, , , , , , , , , , , , , , , , , , ,	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	dann 1 1	100 400	
	er on the	Lill	
10 IAPSEW	ER ON THE		
OF OF ST. TYPE	E OF STREET	11.0.1	k
THE PREMISES BEING LOT NO. GILGI	Vest Va , Hous	SE NO. 54	15
//			
WORK TO BE DONE IN ACCORDANCE WITH ORDINAN	ICE NO. 2323, DL	ILY PASSED BY TH	E CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR	na		
Note This permit covers work o	utside of buil	lding only. A	Anv work ir

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.