Nº 7256

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-24-60 HOUSE NO. 217	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 140 EAST of M 7 Deep Output Deep Output Distance From First Manhole Down Stream To Deep Distance From First Manhole Down Stream To Deep Distance From First Manhole Down Stream To Deep Distance From First Manhole Down Stream To Distance Distance From First Manhole Dis
WAS LATERAL AT CURB? V 55	and the second of the second o
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR HORRAN
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	GARRE 7
	700
en de Nadiones (no esta por la capación de la capa La capación de la cap La capación de la capac	200 → E
N	——————————————————————————————————————
SIGNED ROY Lathours INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 7256

PERMIT TO TAP SEWER

Less Are present a series to the present the first the present that the present the presen
MASSILLON, OHIO, MALO 21) 19
RECEIVED OF JOANNE HASTED FEE OF 5 5
FOR WHICH PERMISSION IS GRANTED
TO TAP SEWER ON THE MALITY
OF St. TYPE OF STREET ACAD
THE PREMISES BEING LOT NO. // L/44 , HOUSE NO. 2/7
7,7,7
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.