


No 7257

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-27-60 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM PIPE ON WYE 143' EAST OF M
HOUSE NO. 1621
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? NO
WAS ATTACHED TO MAIN NAS NAME OF CONTRACTOR H. ASTON
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

~~9-11~~
7-10

Mark ledger or with
5 Apts

10-6-60 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

No. 7257

MASSILLON, OHIO, 6/21 1960

RECEIVED OF Edo Albert H. H. H. FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED Domestic Bathroom

TO TAP San SEWER ON THE 1

OF Lyndale Way E. AVE. ST. TYPE OF STREET Paved

THE PREMISES BEING LOT NO. 1953-52, HOUSE NO. 1621

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR J. A. Asten

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.