Nº 7266

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7/8/60	IF SO HOW AND LOCATION FROM 153 - 80
HOUSE NO. 1736	
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBI 10	
WAS ATTACHED TO MAIN 1955	NAME OF CONTRACTOR a. J. Diana
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED.
	<-15'→\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
N	
and the training of the second	The state of the s
•	8
e de la companya del companya de la companya del companya de la co	FLOW >
rel M C 5. DA	/55
SIGNED William C. Miles	FILED AT ENGINEER'S OFFICE 12-1-60
	sa li likazar meranggalak berampili di palih kebilang merupak bilanggalan berampili berampili berampili beramp
DEMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	19
RECEIVED OF A DIAMA	00	FEE OF S
FOR WHICH PERMISSION IS GRANTED Standar	1 Harring Con	
TO TAPSE	A = A	
OF /// / AVE. TY		
THE PREMISES BEING LOT NO. 12105	, HOUSE NO	26
WORK TO BE DONE IN ACCORDANCE WITH ORDINARY RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	ANCE No. 2323, DULY PASSED BY	THE CITY COUNCIL
NAME OF CONTRACTOR OF THE		
Note This permit covers work	outside of building only.	Any work ir

walls of building is subject to Massillon Board of Health Regulations.