Nº 7282

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 1/16/60	_ IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST-MANHOLE DOWN STREAM TO DITCH AT 35' FROM UPSTREAM MY 9'D CURB LINE AND DEPTH 35' FROM UPSTREAM MY 9'D
WAS LATERAL AT CURB? YES	
WAS ATTACHED TO MAIN YES	- NAME OF CONTRACTOR #J. DIANA
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
	-125
en e	and the support of th
	and the second of the second o
	75
	776
SIGNED William C. While	D 35 - FLIN >
/ INSPECTOR FOR C	

MURCHESTER VS. GERMANIACION OF OF OFFICE OF THE DIRECTOR OF PUBLIC SERVICE CHURENOS POSO CASO COMPREMIT TO TAP CRWER-

	CAL OF HER
reform a for a galar was design to a Massillon, Ohio,	1 7/1/ 00 MAG
$\widehat{}$	13
RECEIVED OF	FEE OF 5.
FOR WHICH PERMISSION IS GRANTED	els Por
TO TAP SEWER ON THE	La company and the second
of 2 1 AVE. ST. TYPE OF STREET	the configuration of the second
THE PREMISES BEING LOT NO. 12045 , House	NO. 52/9
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY	PASSED BY THE CITY COUNCIL

RULES OF THE DEPARTMENT OF PUBLIC SERVICE

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.