## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-3-60	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED // WAS LATERAL AT CURB? Yes	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT 182 North of M. 7 Dee
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
N -	700
A Section 2 of the Section of the Control of Control     The Control of Control     The Control of Control     The Control of Control     The Control	38' 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
R	192
SIGNED NISPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

14.5	7289			LKW.	II I	UIA	r Se	WEK	
				Mass	ILLON, O	H10,	8/2		19́
Red	CEIVED OF	<u>H.</u>	1260					FEE OF \$	<u>5</u>
FOR WHICH	H PERMISSION I	S GRANTED	a.	, O	000	, 1		**	
TO TAP	1 1			SEWER ON	THE	(	= - 2		
OF	27	*/ >	)/// AVE	TYPE OF	STREET	·	( ed)		
THE PREMI	ISES BEING LO	r NO	379	••••• <u> </u>	, но	OUSE NO	176		
WORK TO	BE DONE IN A	CCORDANC	E WITH ORE	INANCE N	o. 2323,	DULY PASS	SED BY TI	RE CITY CO	UNCIL
	THE DEPARTM	ENT OF PUE	SLIC SERVICE	i. IIII		· · ·	·.		
•									

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.