

Nº 7311

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-25-60

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

297' W. of RA 6 1/2' D.C.

HOUSE NO. 2229

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Joe & Joe

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N

0 197' 19' 0 45° B & W D.C.

SIGNED

Paul L. Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

2-6-62

17-37

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

8-42
Nº 7311

PERMIT TO TAP SEWER

MASSILLON, OHIO,

Aug 27-

19

RECEIVED OF

Mr. S. Bladen

FEE OF \$

5⁰⁰

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San

SEWER ON THE

South

OF

Linton Cr. N.W.

AVE.

ST. TYPE OF STREET

Hard Surface

THE PREMISES BEING LOT NO.

#12117

HOUSE NO.

2227

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Joe & Joe

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.