FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	GO E. OF UPSTreAM. IF SO HOW AND LOCATION FROM TAPPED Brookfield Trun FIRST MANHOLE DOWN STREAM.
HOUSE NO. 2222	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	in the state of th
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR LIEU & Jan
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED
	70
Land the second	in the
$\dot{\mathcal{N}}$	0 22 12 10ecb = 24" 60'
Pad I maple	TAPPED WITH SADDLE - 45°BEND
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
	Tand to so, so ten up the select products of the epitop. 2-6-62
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 7320

PERMIT TO TAP SEWER

MASSILLON, OHIO, Aug 27	19
RECEIVED OF N T S BINES FEE OF \$	<u>~5 °</u>
FOR WHICH PERMISSION IS GRANTED $Same$	
TO TAP Say SEWER ON THE South	tury (in the contract of the c
OF MAUC TOWER N.W. AVE. TYPE OF STREET HAY OF SILV LOS	
THE PREMISES BEING LOT NO. $12/27$, HOUSE NO. 2233	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	COUNCIL
NAME OF CONTRACTOR	•

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.