N° 7327

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-7-61	IF SO HOW AND LOCATION FROM WYE 59 SOUTH of MILDE
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBY	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR JAC V Josephan
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	14
	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~
	The second of the second secon
	C03/9
	5-91-0
SIGNED Now Yatha	FILED AT ENGINEER'S OFFICE 2-6-62
INSPECTOR FOR CIT	
REMARKS	

942

Nº 7327

PERMIT TO TAP SEWER

, i	MASSILLON, OHIO, (1.1977 19	
RECEIVED OF 11 9 & CO	dres FEE OF \$ 50	
FOR WHICH PERMISSION IS GRANTED Same	•	
TO TAP AND SEWE	•	
of Standish 11 W. AVE. TYPE	OF STREET Hand Junface	
THE PREMISES BEING LOT NO. 12134		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC		
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR		
	itside of building only. Any work in	
walls of building is subject to Massillon Board of Health Regulations.		