Nº 7345

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-29-6	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 9/5	- Z'a
SIZE OF PIPE USED 411	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH S15 HEIOS F. CURD I S S
WAS LATERAL AT CURBY YES	en en en la 2022 de la composició de la com ■
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
	25
. Konstruktur (n. 1886)	. Other than the state of the s
	and the first and the surface control of the Contro
\sim	8,0 7/10,
	SOUTH CURE 5161
SIGNED Not Nathan	FILED AT ENGINEER'S OFFICE
REMARKS	

2	•	3	3			
	,	/ } -	- 2	5	 6	0

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, $9/29$
RECEIVED OF RECEIVED OF STATE OF \$5
FOR WHICH PERMISSION IS GRANTED Christ
TO TAP SEWER ON THE
of Atule 7 6 ST. TYPE OF STREET
THE PREMISES BEING LOT NO. 1212 13 HOUSE NO. 915
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
2711.62

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.