Nº 7366

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-23-68	
DATE INSPECTED	IF SO HOW AND LOCATION FROM THEPPED 178 W. OSM. 81
HOUSE NO. 1916 - 1918	
SIZE OF PIPE USED	DISTANCE FROM FIRST-MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBI	and the second of the second o
WAS ATTACHED TO MAIN V P C	NAME OF CONTRACTOR WILLIAM
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
· · · · · · · · · · · · · · · · · · ·	1 the second sec
	h (= 2'0
gert er manner i regen brev til til til som	and the state of t
	and the contract of the contra
رائي دي. مستخصص مارون د مستخصص مارون د	18. 8. 5 178
SIGNED Roy Lather	TAPPORT MAIN UNDER SIDEW,
INSPECTOR FOR C	
REMARKS	

Nº 7366 PERMIT TO TAP SEWER

and the second seco		MASS	ILLON, OHIO,	Muss.	23	_19
RECEIVED	OF JUANNE	19 71	rhan	orientaria de la compansión de la compan	_ FEE OF \$	- c'-;
FOR WHICH PERM		Paul	Kelle		n in de meet de property.	
TO TAP	Add 11)		I THE	ed de tet l		• .
of \\ \frac{1}{1/1}		AVE. ST. TYPE OF S		Buch	Late money	<u> </u>
THE PREMISES BE		870		NO. 19	16-191	8
- 1 - 1	·	/ -			•	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR HANGEL A. MARTINE

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.