Nº 7383

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO.	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB'LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATE	
SIGNED	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CIT	
대한 대통령대 한 경험 전체 한 경험 이 전 한 경우는 경우를 받는 것이 되는 것이 없는 것이 없는 것이 없는 것이 없는 것이 없는 것이다. 그렇게 되었다는 것이 없는 것이다.	

office of the director of public service
Nº 7383 PERMIT TO TAP SEWER

1		Massillon, Ohio, The Massillon, Ohio
180		RECEIVED OF HISTORIAN TOWN I AND - CONTROL FEE OF \$ 5
13 Q000 -		FOR WHICH PERMISSION IS GRANTED day with Day 11 August Sew
		TO TAP 57 11 NAITH MITMAGENERON THEWA. 35 th each of each
	Ċ.	OFAVE. TYPE OF STREET
	/	THE PREMISES BEING LOT NO. CAUNA LEASE. HOUSE NO.
		WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PABSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
		NAME OF CONTRACTOR A CONTRACTOR
	galler, sommer fremende generale en	Note This permit/covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.