Nº 7392

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-15-61	,	
DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 337		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 47 FAST OF CURB LINE AND DEPTH	M. 7 Deri
WAS LATERAL AT CURBY	an ang manganang managan <i>m</i> inggan sa sa pangan na mangan sa sa mangan sa mangan m Tangan sa	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR 9	C-cana
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.	
and the first time and the second section of the second		
V ·	70 > \2	Perop Llw
William I		
SIGNED ROY Zatha	FILED AT ENGINEER'S OFFICE	
INSPECTOR FOR CIT	l walli seni dasa misi inna i saliki na ina sili ny	

No 7392 PERMIT TO TAP SEWER

MASSILLON, OHIO, MARYLL 15 19
RECEIVED OF PROPERTY OF STEE OF 5 5
FOR WHICH PERMISSION IS GRANTED
TO TAP AND SEWER ON THE MALLEL
OF ALLEY ME ST. TYPE OF STREET HALL TOP
THE PREMISES BEING LOT NO. 11394 , HOUSE NO. 337
/

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.