## Nº 7394

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3 - 22	FIRST MANHOLE DOWN STREAM 411 135 SOUTH OF ME
HOUSE NO. 5/6-18-20-	22-24
· · · · · · · · · · · · · · · · · · ·	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	<u> 6 martin de la companya del companya de la companya del companya de la companya</u>
	CS NAME OF CONTRACTOR OF TOURS
SHOW BY DIAGRAM RELATION	OF LATERAL TO WALL OF BUILDING SERVED.
	C'beelo.
	Control of the contro
or own or N	The state of the s
	The second secon
4.基点 20.数方	135' 49' K8'DeeP
R. J.	
SIGNED / INSPECTO	FILED AT ENGINEER'S OFFICE
REMARKS	

## 7/28/61 10 7394

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	en e	MASSILLON, C	OHIO, MAR	1/2/ 19
	RECEIVED OF MOCK			_ FEE OF 55
	HICH PERMISSION IS GRANTED_	21	,	
TO TAP	<u>saw</u>		ing dia menggan dan kampun. Terhapan dan kampun dan kampun dan	
OF	DET MU	.4	der 1 516-5	18-520-522
THE PF	REMISES BEING LOT NO.	(1/8/, +	HOUSE NO.	THE CITY COUNCIL

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A MARKET

Note This permit/covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.