## Nº 7448

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-7-6 IF SO HOW AND LOCATION FROM Y" 106 WEST OF ME 79	
HOUSE NO	
SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
10 N	
SIGNED WILLIAM HAMMEN FILED AT ENGINEER'S OFFICE	

8-21-61

 $\mathbf{N}$ ? 7448 $\checkmark$ 

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

RECEIVED OF Harry B.	MASSILLON, OHIO, acq 5
FOR WHICH PERMISSION IS GRANTED	l Aser
	WER ON THE MARTIN
OF Bordew A. W. AVE. TY	, <del>~~</del>
THE PREMISES BEING LOT NO. $12269$	HOUSE NO. 1242
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	E No. 2323, DULY PASSED BY THE CITY COUNCIL, AND

OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR HANGE B. MANTHE

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.