

Nº 7450

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-8-61

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM "Y" 186' West of MH 8 1/2 D

HOUSE NO. 2206

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR S. LAUGHLIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Ray Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

18
Nº 7450 ✓

3/7/01
60
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Aug 7 1901

RECEIVED OF Earl Laughlin

FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED To S. Knudsen

TO TAP Yew

SEWER ON THE North

OF W. H. Knudsen

AVE.
ST. TYPE OF STREET West

THE PREMISES BEING LOT NO. # X 12316

HOUSE NO. 7206

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Earl Laughlin

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.