Nº 7461

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-18-61	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 947		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 10,1 SAUTH MA 5 DEEP	
WAS LATERAL AT CURB? VES		
WAS ATTACHED TO MAIN Mai	NAME OF CONTRACTOR REMIEV	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	3/2/2	
- N	3	
	5/bEFP 3'	
William Glemm		
SIGNED WWW. INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	

Nº 7461

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	8/,00
MASSILLON	, Оню, / Г О1
RECEIVED OF TONI COU	FEE OF \$5
FOR WHICH PERMISSION IS GRANTED Of A A D	Mure.
TO TAPSEWER ON THE_	20 W
OF 20 + D & AVE. TYPE OF STREET	dent
THE PREMISES BEING LOT NO	HOUSE NO. 247
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323,	DULY PASSED BY THE CITY COUNCIL, AND

OF THE DEPARTMENT OF PUBLIC SERVIC

AME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.