Nº 7487

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-19-61	FIRST MANHOLE DOWN STREAM WYE 108 WEST of HE & Dec	
HOUSE NO. 22/3	·	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? No		
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR E. Smuddlin	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	0-108' 14' 28'0	
SIGNED ROY Sathan INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE	
REMARNS	- Control of the cont	

Nº 7487

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

, somer.	Margua en O	10/19
RECEIVED OF COLUMN	Massillon, Of	ation () FEE OF S 5
OR WHICH PERMISSION IS GRANTED	Lud dod	(Post
O TAB	SEWER ON THE	<u> </u>
Chale Lead	AVE. TYPE OF STREET	dest
HE PREMISES BEING LOT NO	Job 71031, HO	DUSE NO. 22/3
ORK TO BE DONE IN ACCORDANCE V	/23 3∯ WITH ORDINANCE No. 2323, DUL	Y PASSED BY THE CITY COUNCIL, AND
F THE DEPARTMENT OF PUBLIC SER	RVICE.	

Co. NAME OF CONTRACTOR Kara Marie Co.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.