

Nº 7495

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-7-61

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2306

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


143' WEST MH 6' DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN —

NAME OF CONTRACTOR Laughlin

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 7495 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, Nov 2 1911

RECEIVED OF Lueddke Co

FEE OF \$ 15.00

FOR WHICH PERMISSION IS GRANTED " "

TO TAP San

SEWER ON THE " "

OF Rhode Island, D.E.

AVE.
ST.

TYPE OF STREET St. A

THE PREMISES BEING LOT NO. Lot #12, 86326

HOUSE NO. 2306

12320

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Laughlin

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.