## Nº 7498

REMARKS .

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-8-41	IF SO HOW AND LOCATION FROM 191' WEST OF 14 61 DEEP
HOUSE NO. 2324	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN 15	NAME OF CONTRACTOR LAYGHIIN
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	18'
	THE STATE OF THE S
·	Costago, 45° BENCO
SIGNED William Hums	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CIT	

## Nº 7498

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

RECEIVED OF	Lu	dded	MASSILLON	, Оніо,	1602	1
WEGELVED OF		//	11			
FOR WHICH PERMISSION	N IS GRANTED					
TO TAP DALC	ci.	SE	WER ON THE_			
TO TAP LACE	Maud	AVE.	PE OF STREET	d	42	
THE PREMISES BEING L	OT NO.	15- CA	(326	, HOUSE NO.	2320	
WORK TO BE DONE IN A						
AS THE DESABELLENT OF	e Busile Se					

NAME OF CONTRACTOR ALLEMANTE

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.