

Nº 7499

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-7-61

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 55' SOUTH OF MH 9' DEEP

HOUSE NO. 262

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Laughlin

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 7499 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, Mar 2 1911

RECEIVED OF Luedd Co.

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED _____

TO TAP same

SEWER ON THE _____

OF Arthur St

AVE.
ST. TYPE OF STREET dist

THE PREMISES BEING LOT NO. lot #25 blk. 326

HOUSE NO. 262

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Loughlin

Note: This permit covers work outside of building only. Any work :
walls of building is subject to Massillon Board of Health Regulations.