

Nº 7500

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-6-61

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

150' SOUTH OF MH 10' DEEP

HOUSE NO. 272

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 12"


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Laughlin

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



SIGNED

William Hammer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 7500 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Nov 2 1911

RECEIVED OF Liddell Co.

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED _____

TO TAP Raw.

SEWER ON THE _____

OF Arthur St.

AVE.
ST. TYPE OF STREET West

THE PREMISES BEING LOT NO. Lot # 26 Ch 326

HOUSE NO. 272

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Liddell

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.