Nº 7577

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-12-62	IF SO HOW AND LOCATION FROM WYE 135 W. OF M 8 OF
HOUSE NO. 24/3	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? No	
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
en de la companya de La companya de la co	C1:3
	Q 135' 80 7 10'
·	A STATE OF THE STA
SIGNED ROLL INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICEY
REMARKS	The state of the s

office of the director of public seing permits to tap sewer

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTO

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.