

Nº 7600

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-11-62

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 109' NORTH OF MH 8 1/2' DEEP

HOUSE NO. 313

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William Hammer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 7600

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

July 5

RECEIVED OF

R. G. Marks

FEE OF \$

5

FOR WHICH PERMISSION IS GRANTED

Ludded Co.

TO TAP

San

SEWER ON THE

West

OF

Underhill Dr. SE

AVE.

ST. TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

12326

HOUSE NO.

313

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. G. Marks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.