## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 4-16-62           | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|----------------------------------|---|
| HOUSE NO. SCC                    | DISTANCE SPON SIDET MANUALS                           |
| SIZE OF PIPE USED                | DOWN STREAM TO DITCH AT 70 E. OF MY CIDEE             |
| WAS LATERAL AT CURB? 15          | $\mathcal{P}$   |
| WAS ATTACHED TO MAIN             | NAME OF CONTRACTOR                                    |
| SHOW BY DIAGRAM RELATION OF LATI | ERAL TO WALL OF BUILDING SERVED.                      |
|                                  |   |
|                                  |   |
| V                                | 28 · · · · · · · · · · · · · · · · · · ·              |
| Ň                                | 31  |
|                                  | 20  |
| SIGNED Winspector For CI         | FILED AT ENGINEER'S OFFICE                            |
| REMARKS                          |   |

Nº 7616 (ala)

## PERMIT TO TAP SEWER

|   | MASSILLON, OHIO, aug 14                                 |
|---|---|
| RECEIVED OF Maymon                      | d Remember  |
| R WHICH PERMISSION IS GRANTED           | Potent E. Owen  |
| TAP Daw                                 | SEWER ON THE Thortie                                    |
| Wellman E                               | AVE. ST. TYPE OF STREET Hardenface                      |
| e premises being lot no. $\frac{277}{}$ | 8 HOUSE NO. 866   |
| DV TO BE DONE IN ACCORDANCE WIL         | TH OPDINANCE NO 2323 DILLY PASSED BY THE CITY COLINCIL. |

OF THE DEPARTMENT OF PUBLIC SERVICE.

AME OF CONTRACTOR Haymond Newler

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.