

10-48

Nº 7617

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1-24-62

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM ?

HOUSE NO. 118

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH ?



SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? NO


WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR R. Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



THIS LINE IS BY THESE HOUS



SIGNED Roy Lenthall

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 10-26-62

REMARKS

№ 7617

RE 14

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO

Aug 14

RECEIVED OF

Raymond Remley

FEE OF \$

5

FOR WHICH PERMISSION IS GRANTED

Mary K. Lusher (et al)

TO TAP

San.

SEWER ON THE

North

OF

Lane at. S.W.

AVE.

ST. TYPE OF STREET

ciled

THE PREMISES BEING LOT NO.

9969

HOUSE NO.

118

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.