Nº 7618 (FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-13-62	IF SO HOW AND LOCATION FROM PIPE IN MY 8 DEEK
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR P. Weenley
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED.
	8" StuB/N
en e	MA PUTG"PIPE
N — —	811
	0 = 8 6.
Roll of the	
SIGNED INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

Nº 7618 PE	RMIT TO TAP SEWER
MASSIL	LON, OHIO, aug 14-
RECEIVED OF RAYMOND Rember 18 Coule FOR WHICH PERMISSION IS GRANTED Hrs. Ect.	y FEE OF \$5°
FOR WHICH PERMISSION IS GRANTED This. Ecte	- Taylor
TO TAP SEWER ON 1	THE East
TO TAP Daw. SEWER ON TO TAP DAVE. OF WALL FILE OF ST. TYPE OF ST.	REET East Dirt
and the second s	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 23	

OF THE DEPARTMENT OF PUBLIC SERVICE.

AME OF CONTRACTOR / Caymond Cember

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.