## Nº 7647

REMARKS \_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-3-62	IF 50 HOW AND LOCATION FROM
HOUSE NO. 72 /2	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT
WAS LATERAL AT CURB? YES	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR JOE & JOE
SHOW BY DIAGRAM RELATION OF LAT	FERAL TO WALL OF BUILDING SERVED.
	4
ing the second of the second o	7.8 W
	7/0 7/1
	K-1101
SIGNED William Ham	Mich Filed at Engineer's Office
INSPECTOR FOR	

10/7/67

## Nº 7647

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, 7,
Chr. V Co	
RECEIVED OF	FEE OF \$
FOR WHICH PERMISSION IS GRANTED THE	ldel 160.
то тар вами вем	VER ON THE SOLET NORTH
of Cambridge AVE. TYP	E OF STREET Alis
THE PREMISES BEING LOT NO. 13954	HOUSE NO. 2212

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR ( ) ae 7 ( ) ae

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.