

Nº 7659

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-25-63

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 326

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


247' EAST 5' H 7' DEE
LAT. FROM PROP. LINE TO MAIN O.R.

WAS LATERAL AT CURB? PROPL. YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR A. J. DIANA

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

✓
Nº 7659

12-21-63 16-3
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 22

RECEIVED OF A. J. Diana

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED William Grishmer

TO TAP San

SEWER ON THE North

OF Sandy St.

AVE.
ST. TYPE OF STREET Oiled

THE PREMISES BEING LOT NO. # 11377

HOUSE NO. 326

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Diana

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.