

No. 7692

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-26-63

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 427

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH EAST OF MH 56' 8" DEEP

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR BEAVER

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hamner

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

← 56'

REMARKS _____

16-40
12-21-63

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

✓
No 7692

PERMIT TO TAP SEWER

MASSILLON, OHIO, August 21

RECEIVED OF

Ralph Brance

FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED

Removal of water from Arthur Dale

TO TAP

Sanitary

SEWER ON THE

South

OF

Taggart

AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

11345

HOUSE NO.

427

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Beaver Construction

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.