Nº 7701 AND SIGNED WHEN RETURNED

DATE INSPECTED 10-30-63	IF SO HOW AND LOCATION FROM WYE 205 W. 05 MONTRUNK
HOUSE NO 882	
SIZE OF PIPE USED 6 4 4"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? No	NAME OF CONTRACTOR P. Marks CLEAN OUT
WAS ATTACHED TO MAIN YES	The state of the s
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
	ERAL TO WALL OF BUILDING SERVED.
e dominacije koj per ne degala e objekti. Podala ka	3
	2 5°
The second communication of th	A CONTRACTOR OF THE STATE OF TH
SIGNED Port Sattle	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CI	TY THE PARTY OF TH
REMARKS	V

Nº 7701

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MAS	SILLON, OHIO, Clared 30 19
RECEIVED OF N. J. Marker	FEE OF \$
	neig
FOR WHICH PERMISSION IS GRANTED	
TO TAPSEWER O	N THE West SIDE
or Eldow A. T. W AVE. ST. TYPE OF	and the contract of the contra
THE PREMISES BEING LOT NO. # 10205	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2	2323, DULY PASSED BY THE CITY COUNCIL, AND RULES
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR J. J. Mark	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.