1000 I TO TO THE FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 7702 AND SIGNED WHEN RETURNED

DATE INSPECTED 11-7-65	FIRST MANHOLE DOWN STREAM
HOUSE NO. 720	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 38 EAST OF MY 7 DE CURB LINE AND DEPTH 38 EAST OF MY 7 DE
WAS LATERAL AT CURB? VES	
WAS ATTACHED TO MAIN. NO	NAME OF CONTRACTOR - Cl. Diana
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.
N	
	70
0 -	
SIGNED INSPECTOR FOR	FILED AT ENGINEER'S OFFICE
REMARKS	

2-20-64

OFFICE OF THE DIRECTOR OF PUBLIC SEI

Nº 7702

PERMIT TO TAP SEWER

	Massillon	, OHIO, Africa	about I 1
RECEIVED OF	Oberlin		FEE OF \$5.0
FOR WHICH PERMISSION IS GRANTED	* - <u>u</u> . · <u>u</u>	***	
TO TAP Sanitary	SEWER ON THE	Harth	
or Sand Brise N		Chip v.	Sul_
	11365	, HOUSE NO.	?o
WORK TO BE DONE IN ACCORDANCE W	ITH ORDINANCE No. 2323, I	DULY PASSED BY THE	E CITY COUNCIL, AŅI

a. J. Diava

OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.