Nº 7705

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-10-C	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 725		
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	MY 9 DEEF
WAS LATERAL AT CURB? VES	uni di salah dalam dan dan kecamatan dan bermatan dan bermatan dan bermatan dan bermatan dan bermatan dan berm —	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR HURBE	411
SHOW BY DIAGRAM RELATION OF LAT	FERAL TO WALL OF BUILDING SERVED.	A101K
and the second of the second o	and the state of t	
	A second	STOOP
	N	52
om menty a boson make an other Basil T		15. REND
SIGNED R. Latham	FILED AT ENGINEER'S OFFICE	′→
INSPECTOR FOR C		

Nº 7705

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

-160 27

		Massillon, Ohio,		
RECEIVED OF.	TulenM. C	ades		FEE OF 5
i	Thus	Durch		
FOR WHICH PERMISSION	N IS GRANTED	# A1-28: mm		
- Jane		- 30	Jan L	
TO TAP	5E\	VER ON THE		
Word run	AVE.	PE OF STREET	Eclip	
THE PREMISES BEING L	# 12187-90		SE NO. 775	
				•
WORK TO BE DONE IN A	CCORDANCE WITH ORDINANC	E No. 2323, DULY	PASSED BY THE C	ITY COUNCIL, ANI
· · · · · · · · · · · · · · · · · · ·	Harry Unban	J	· · · ·	
NAME OF CONTRACTOR	'—————————————————————————————————————			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.