Nº 7710

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $\frac{1-2-64}{137}$	FIRST MANHOLE DOWN STREAM 42 FAST of MACO 2 NO ST
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBI	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
	N 5 NHO NO PEOL
tion of the state	
SIGNED ROY Lines for CI	FILED AT ENGINEER'S OFFICE 206
ng san ive san Verilland de la san de la	

Nº 7710

OF THE DEPARTMENT OF PUBLIC SERVICE.

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	M.	Aşsıllon, OH	io. Jan	J 20 1
RECEIVED OF FRYMEN A	L H	culing		FEE OF \$
, T 2		2 de		
TO TAP Saw. Jederal 1/W.	AVE, _ ST, TYPE O	F STREET	First.	
THE PREMISES BEING LOT NO.		, но	USE NO	137
WORK TO BE DONE IN ACCORDANCE WITH OF	RDINANCE NO	ว. 2323, อยนา	Y PASSED BY	THE CITY COUNCIL, ANI

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.