

✓
No 7719

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-1-69

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1209

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

154' S. of MH 8' DEEP



WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

H. Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

W. HAMMER
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

154

N^o 7719

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO

March 30

RECEIVED OF

Harry Urban

FEE OF \$

5

FOR WHICH PERMISSION IS GRANTED

TO TAP

Sewer

SEWER ON THE

West

OF

14th St. S.W.

AVE.
ST. TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

2945

HOUSE NO.

1209

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harry Urban

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.