

✓
Nº 7721

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-2-69

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1103

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

6' N. of MH 8' DEEP



WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

Joe E. Joe

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

R. HALTER

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

✓ ✓
N^o 7721

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO

April 1

RECEIVED OF

Joe & Joe

FEE OF \$

5⁰⁰

FOR WHICH PERMISSION IS GRANTED

James Ransom

TO TAP

San

SEWER ON THE

West

OF

2nd St. N.E.

AVE.

ST. TYPE OF STREET

Paved

THE PREMISES BEING LOT NO.

12295

HOUSE NO.

1103

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Joe & Joe

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.