Nº 7746 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-23-69	I IF 50 HOW AND LOCATION FROM
	FIRST MANHOLE DOWN STREAM
HOUSE NO. FOX	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT GURB' LINE AND DEPTH OF THE CONTROL OF TH
WAS LATERAL AT GURB?	Property of the second second second
WAS ATTACHED TO MAIN ACT	NAME OF CONTRACTOR H. URBAN
SHOW BY DIAGRAM RELATION OF LATE	i .
	1
and the first of the state of t	The second state was a same of the second
<u> </u>	the control of the co
N.	C/2 1 1 10 1
e e e e e e e e e e e e e e e e e e e	- 3/9 Tre
R. J. Thomas	481
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE TO
REMARKS	And Markey Control of the left of the control of th
REMARKS	

Nº 7746

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	Massillo	ON, OHIO, alig.	8
RECEIVED OF Have	influtions	· · · ·	FFF OF \$
OR WHICH PERMISSION IS GRANT	Energ Caller.	eye.	
O TAP Same Taref	SEWER ON THE	South	
Janinice et.	N.E. AVE.	ET Dist	
HE PREMISES BEING LOT NO.	t. 11696e		5
YORK TO BE DONE IN ACCORDANG	E WITH ORDINANCE No. 2323	3, DULY PASSED BY THE	CITY COUNCIL, AN

NAME OF CONTRACTOR Having Urlians

OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.