Nº 7749

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-13-64 IF SO HOW AND LOCATION FROM WYE 109'S, OF AH 11 DE
HOUSE NO. 578
SIZE OF PIPE USED 6 CURB LINE AND DEPTH
WAS LATERAL AT CURBI NO
WAS ATTACHED TO MAIN VIET NAME OF CONTRACTOR HORAN
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
<u> 15' . </u>
N - 190
30,000
13
Post
SIGNED THE INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE
randa de la completa de la completa REMARKS

1409 1451

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

RECEIVED OF	Jany 1	Viba	MASSILLON, OH	io. Clug.	(2) FEE OF \$ 5
FOR WHICH PERMISSION I	16	all	Cew.		
TO TAP		SEW	/ER ON THE	East	
of_		AVE. _ ST. TYP	E OF STREET	Giled	
THE PREMISES BEING LOT	NO. //2	82	, ног	JSE NO	48
	•				

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.