

N^o 7752

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-8-64

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 620

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 283' EAST OF M 8' DEE
CURB LINE AND DEPTH



WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR H. URBAN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
↑
L



SIGNED

Roy Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7752

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Sept 7 2

RECEIVED OF Geo. Hartler

FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Harry H. H. H.

TO TAP Sanitary

SEWER ON THE North

OF Sheri

AVE.

ST. TYPE OF STREET Hard Surface

THE PREMISES BEING LOT NO. 11470

HOUSE NO. 1020

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harry H. H. H.

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.