## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN DETURNED

DATE INSPECTED 9-16-64	IF SO HOW AND LOCATION FROM PUT WYE IN 7 FAST C	FM
HOUSE NO. 2940		9
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLES CONTROL OF THE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	٠.
WAS LATERAL AT CURB? NO		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR HORBAN	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
	5 to 1 to	_
	and the second of the second o	
The first of the f	1	
R. D.	\$\frac{1}{2}8\rightarrow{\pi}{2}	
SIGNED OF When INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 9 DP	
REMARKS		
ECMAENS		

## Nº 7755

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	Massillon, Ohio
RECEIVED OF Javan Ch	MASSILLON, OHIO, 10,
FOR WHICH PERMISSION IS GRANTED Car	l Open
TO TAP	SEWER ON THE Horth
TO JAP Jam.  Jordon 7. W. AVE.	TYPE OF STREET duit
THE PREMISES BEING LOT NO. 1 6. 21	8 15108 HOUSE NO. NONE 2940
	ANGE NO 2323 DULY PASCED BY THE GITY COUNCIL AN

OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harry Ulwan

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.