

✓ 18.

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 7786

DATE INSPECTED 4-1-65

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM STUB IN MH 10' DEEP

HOUSE NO. 2336

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR R MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7786

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Apr. 1

RECEIVED OF R. S. Marks

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED Lisle's Buick

TO TAP Sanitary

SEWER ON THE North

OF Henochs Bay E.

AVE.

ST. TYPE OF STREET Black L. p

THE PREMISES BEING LOT NO. PC-417-A

HOUSE NO. 2926

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. S. Marks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.