

Nº 7799

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-20-65

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1121

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

19' WEST OF M/H 8' DEEP


WAS LATERAL AT CURB? ^{Prop} YES

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR

R. MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 7799

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, May 17

RECEIVED OF Hardt Construction

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP Sanitary

SEWER ON THE West

OF Second St

AVE.
ST. TYPE OF STREET Wooden

THE PREMISES BEING LOT NO. 12271

HOUSE NO. 1121

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR F. G. Marke

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**