## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 7802 AND SIGNED WHEN RETURNED

DATE INSPECTED 6-2-65	IF SO HOW AND LOCATION FROM IN MA 4 DEEP		
HOUSE NO. 20	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT		
SIZE OF PIPE USED	CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR P. MARKS		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	7201		
N ————————————————————————————————————	136		
SIGNED P. Lecture	TAPPED MY  FILED AT ENGINEER'S OFFICE		
REMARKS			

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

## $N^{\circ}$ 7802

	MASSILLON, C	OHIO 11 11 11 22
RECEIVED OF	Massillon, C	FEE OF S
FOR WHICH PERMISSION IS GRANTED	Eway of Shi	defindent
TO TAP COLLECTION OF	SEWER ON THE	76 M
of Hoich of	.AVE. ST. TYPE OF STREET	10 R + Concret
THE PREMISES BEING LOT NO.	4.2577	IOUSE NO 20
WORK TO BE DONE IN ACCORDANCE OF THE DEPARTMENT OF PUBLIC SE		LY PASSED BY THE CITY COUNCIL, AN
NAME OF CONTRACTOR	Mar. Re	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.