

✓ 7-
8-
Nº 7803

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-1-65

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1315

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 133' W. of rd > 1' D.I.E

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR H. Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 7803

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, May 25

RECEIVED OF

Billy Realty Co.

FEE OF

5

FOR WHICH PERMISSION IS GRANTED

Massillon Cabinet Shop.

TO TAP

1315 overlook S.W.

SEWER ON THE

South.

OF

37 E. 1st

AVE.

ST. TYPE OF STREET

Black Top.

THE PREMISES BEING LOT NO.

8873

HOUSE NO.

1315

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Massillon Cabinet Shop. Harry M. M. M.

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.