


N^o 7808

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-11-65IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 940SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 133' N. of MH 7' DEEPWAS LATERAL AT CURB? YESWAS ATTACHED TO MAIN NONAME OF CONTRACTOR R. MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 11-10-65

REMARKS _____

1-21

Nº 7808

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO

June 10

RECEIVED OF

R. S. Marks

FEE OF \$

50

FOR WHICH PERMISSION IS GRANTED

Donald Kandle

TO TAP

Sanitary

SEWER ON THE

East

OF

23rd N.W.

AVE.

ST. TYPE OF STREET

Black Top

THE PREMISES BEING LOT NO.

7336

HOUSE NO.

440

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. S. Marks

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.