## Nº 7811 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED AND SIGNED WHEN RETURNED

| DATE INSPECTED 7-2-65 IF 50 HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|---|
| HOUSE NO  |
| SIZE OF PIPE USED 611 UPDOWN STREAM TO DITCH AT 95 N. 0 \$ UP STREAM JUH    |
| WAS LATERAL AT CURB? VES  |
| WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR A. DIANA                         |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.             |
| \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\                                      |
| AE AE   |
| SIGNED FILED AT ENGINEER'S OFFICE 12.23 -65                                 |

## Nº 7811

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

| adhana cambar ,       | 1               | MASSILLON                               | OHIO, June 15,                      | _ |
|-----------------------|-----------------|---|-------------------------------------|---|
| RECEIVED OF           | Habert          | Long                                    | OHIO, James 15,                     | _ |
| FOR WHICH PERMISSION  | IS GRANTED      | *************************************** |                                     | _ |
| TO TAP Jan            | Francy          | SEWER ON THE_                           | East<br>Grove                       | _ |
| OF 37th A4            | . N. W.         | AVE.<br>ST. TYPE OF STREET              | grave-                              | - |
| THE PREMISES BEING LO | T NO. 0/3       | 174                                     | HOUSE NO. 644                       | _ |
| WORK TO BE DONE IN AC | CORDANCE WITH C | PRDINANCE No. 2323, p                   | DULY PASSED BY THE CITY COUNCIL, AN | ı |

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.